

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

230703

INVOICE

Ref # : 475502

Printed Date: 02/25/2023

Work Completed: 02/20/2023

Dilly Logistics, Inc. - Vandan Vekaria
 7008 92nd Ave. N.
 Brooklyn Park, MN 55445
 Cellular 651-410-4911

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
 Lic # : PLF9068 Odometer In : 25517
 Unit # : 475502
 VIN # : 1F65F5KN2 **M0A16767**

Part Description	Qty	Sale	Ext	Labor Description	Ext
Battery	1.000	185.79	185.79	Work Requested: Backup camera not working	n/c
Job Supplies			9.630	Labor	82.50
				No start at FDX, jump start and get to shop. Charge and test battery, fails testing. Replace battery, clean and tighten connections. Alternator output at 140 amps under load, parasitic draw under 1 amp, both good to run.	
				Labor	55.00
				Inspect RVS system, found no signal from backup camera, trace wiring, loose connection in dash, secure connection. RVS system works normally after repairs.	
				Labor	55.00
				Bulkhead door hard to open, vacuum out sand from tracks, also both front doors. Lube and adjust, doors work fine after repairs.	
				[Recommendations]	
				PM due by 6/2/2023 or 28,763 miles to extend the life of your vehicle.	
				FAI due by 12/31/2023	

Org. Estimate 401.90 Revisions 0.00 Current Estimate 401.90

Labor:	192.50
Parts:	195.42
SubTotal:	387.92
Tax:	13.98
Total:	401.90
Bal Due:	\$401.90

[Payments -]

Vehicle Received: 2/20/2023

Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com