

Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231979

INVOICE

Ref # : 475502

Printed Date: 05/23/2023

Work Completed: 05/22/2023

Dilly Logistics, Inc. - Vandan Vekaria
7008 92nd Ave. N.
Brooklyn Park, MN 55445
Cellular 651-410-4911

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
Lic # : PLF9068 Odometer In : 33925
Unit # : 475502
VIN # : 1F65F5KN2 M0A16767

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	8.500	4.45	37.83	Work Requested: PM, passenger side camera not working	n/c
Filter oil	1.000	8.46	8.46	PM Service	80.00
W/ Washer Fluid	1.000	3.39	3.39	Change oil, oil filter, lube vehicle	
W/wiper blade	2.000	10.53	21.06	Labor	27.50
225/70R/19.5 HMT Deep XT	4.000	198.65	794.60	Replace worn wiper blades	
Tire Disposal	4.000	15.00	60.00	Labor	27.50
Job Supplies			12.750	Inspect RVS system, fond passenger camera unplugged, secure connections. RVS works fine after repairs.	
				Labor tire	120.00
				Replace drive tires, air to 100 PSI. Existing tires were at 4,4,4 & 3/32"	
				[Recommendations]	
				PM due by 9/22/2023 or 37,925 miles to extend the life of your vehicle.	
				FAI due by 12/31/2023	

Org. Estimate 1,258.21 Revisions 0.00 Current Estimate 1,258.21

Labor:	255.00
Parts:	878.09
Tire Fees:	60.000
SubTotal:	1,193.09
Tax:	65.12
Total:	1,258.21
Bal Due:	\$1,258.21

[Payments -]

Vehicle Received: 5/22/2023

Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com