

**Job Site Repair LLC**  
12015 Brockton Ln N  
Maple Grove, MN. 55369  
Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231631**

**INVOICE**

Ref # : 475503

Printed Date: 04/30/2023

Work Completed: 04/28/2023

**Dilly Logistics, Inc. - Vandan Vekaria**  
7008 92nd Ave. N.  
Brooklyn Park, MN 55445  
Cellular 651-410-4911

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL  
Lic # : PLF9069 Odometer In : 42000  
Unit # : 475503  
VIN # : 1F65F5KN7 M0A16764

Part Description	Qty	Sale	Ext	Labor Description	Ext
Flex Shot/Seal	6.000	17.98	107.88	Work Requested: Water in cargo area	n/c
Job Supplies			16.500	Labor	330.00
				Run water over roof and upper seams, no leaks found. Spray under vehicle, leaks around body seams and wheel wells. Pressure wash out cargo area and seal seams with flexshot.	
				<b>[ Recommendations ]</b>	
				PM due by 7/27/2023 or 42,717 miles to extend the life of your vehicle.	
				FAI due by 12/31/2023	

Org. Estimate 462.50 Revisions 0.00 Current Estimate 462.50

<b>Labor:</b>	<b>330.00</b>
<b>Parts:</b>	<b>124.38</b>
<b>SubTotal:</b>	<b>454.38</b>
<b>Tax:</b>	<b>8.12</b>
<b>Total:</b>	<b>462.50</b>
<b>Bal Due:</b>	<b>\$462.50</b>

[ Payments - ]

Vehicle Received: 4/28/2023

Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)