Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231908

Odometer In: 28350

INVOICE Ref #: 475505 Printed Date: 05/19/2023 Work Completed: 05/17/2023

Dilly Logistics, Inc. - Vandan Vekaria

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL

7008 92nd Ave. N.

Cellular 651-410-4911

Lic # : PLF9071 Unit # : 475505

Brooklyn Park, MN 55445

VIN #: 1F65F5KN6 M0A16769

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	8.500	4.45	37.83	Work Requested: PM	n/c
Filter oil	1.000	8.46	8.46	PM Service	80.00
Brake Disc Pads	1.000	72.75	72.75	Change oil, oil filter, lube vehicle	
225/70R/19.5 HMT Deep XT	4.000	198.65	794.60	Labor	220.00
Tire Disposal	4.000	15.00	60.00	During PM inspection found rear brake pads under 3 MM thick,	
Job Supplies			21.000	replace pads.	
				Labor tire	120.00

Replace drive tires, air to 100 PSI. Existing tires were at 5,3,5 &

4/32"

[Recommendations]

PM due by 9/17/2023 or 32,350 miles to extend the life of your vehicle

FAI due by 12/31/2023

Org. Estimate 1,483.39 Revisions 0.00 Current Estimate 1,483.39

Labor: 420.00 Parts: 934.64

Tire Fees:

ees: 60.000

SubTotal: Tax: Total:

68.75 1,483.39

1,414.64

Bal Due:

1,483.39 \$1,483.39

[Payments -]

Vehicle Received: 5/17/2023 Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com