

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231803**

**INVOICE**

Ref # : 479740

Printed Date: 05/12/2023

Work Completed: 05/11/2023

**Dilly Logistics, Inc. - Vandan Vekaria**  
 7008 92nd Ave. N.  
 Brooklyn Park, MN 55445  
 Cellular 651-410-4911

2020 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N F59/53 8 CYL  
 Lic # : PLP5288 Odometer In : 8305  
 Unit # : 479740  
 VIN # : 1F64F5KN4 L0A14769

Part Description	Qty	Sale	Ext	Labor Description	Ext
Job Supplies			5.500	Work Requested: Rear door gets stuck, passenger door hard to open	n/c
				Labor	110.00
				Inspect passenger door, adjust closed striker handle not releasing properly, lube and adjust door. Inspect rear door found top roller brackets came loose. adjust door to not hit cables and lube door, tighten upper brackets. Doors work fine after repairs.	
				<b>[ Recommendations ]</b>	
				FAI due by 10/31/2023	
				PM due by 8/27/2023 or 11,799 miles to extend the life of your vehicle.	

Org. Estimate 115.50      Revisions 0.00      Current Estimate 115.50

<b>Labor:</b>	<b>110.00</b>
<b>Parts:</b>	<b>5.50</b>
<b>SubTotal:</b>	<b>115.50</b>
<b>Tax:</b>	<b>0.00</b>
<b>Total:</b>	<b>115.50</b>
<b>Bal Due:</b>	<b>\$115.50</b>

[ Payments - ]

Vehicle Received: 5/11/2023

Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)