

Job Site Repair LLC

12015 Brockton Ln N

Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE**231621****INVOICE**

Ref #: 501672

Printed Date: 04/29/2023

Work Completed: 04/28/2023**Turn by Turn Deliveries, Inc. - Heith Glenna**

33159 Malmberg Road

Lindstrom, MN 55045

Cellular 651-208-3040

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N F59/53 8 CYL

Lic # :

Odometer In : 8712

Unit # : 501672

VIN # : 1F65F5KN8 M0A01349

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	7.000	4.45	31.15	Work Requested: PM	n/c
Filter Oil	1.000	12.28	12.28	PM Service	80.00
Filter Air	1.000	35.46	35.46	Change oil, oil and air filters, lube vehicle	
Light Amber LED	1.000	10.93	10.93	Labor	27.50
Job Supplies			5.380	Inspect lights, replace burnt out left side hood marker light. All lights work properly after repairs.	

[Recommendations]

FAI due by 1/31/2024

PM due by 8/28/2023 or 12,712 miles to extend the life of your vehicle.

Org. Estimate 209.32 Revisions 0.00 Current Estimate 209.32

Labor:	107.50
Parts:	95.20
SubTotal:	202.70
Tax:	6.62
Total:	209.32
Bal Due:	\$209.32

[Payments -]

Vehicle Received: 4/28/2023

Customer Number : 56

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.comEmail Address: jeff@jobsiterepair.com