

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231854

INVOICE

Ref #: 503534

Printed Date: 05/17/2023

Work Completed: 05/15/2023

Fern, Inc. - Darla Fern
 1325 200th Street
 Baldwin, WI 54002
 Cellular 612-812-6584

2022 Ford - E-450 Super Duty - 7.3L, V8 VIN(K) Gas
 Lic # : Odometer In : 2002
 Unit # : 503534
 VIN # : 1FDWE4FK2 NDC31344

| Part Description | Qty | Sale | Ext | Labor Description | Ext |
|------------------|-------|------|--------|--|--------|
| Fuse tap | 2.000 | 8.25 | 16.50 | Work Requested: Install VEDR camera system, FAI | n/c |
| Fuse Min 25 | 2.000 | 1.00 | 2.00 | Labor | 220.00 |
| Job Supplies | | | 15.250 | Install owner provided VEDR camera system. Remove headliner to install. Reverse camera on constant power, always on, switch to key source power. | |
| | | | | Inspection | 85.00 |
| | | | | Vehicle Inspection & PASSED | |

Org. Estimate 340.11 Revisions 0.00 Current Estimate 340.11

| | |
|------------------|-----------------|
| Labor: | 305.00 |
| Parts: | 33.75 |
| SubTotal: | 338.75 |
| Tax: | 1.36 |
| Total: | 340.11 |
| Bal Due: | \$340.11 |

[Payments -]

Vehicle Received: 5/15/2023

Customer Number : 16

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com