## Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE 231855

**INVOICE** Printed Date: 05/17/2023 Work Completed: 05/15/2023 Ref #: 503535

2022 Ford - E-450 Super Duty - 7.3L, V8 VIN(K) Gas Fern, Inc. - Darla Fern

1325 200th Street Lic#: Odometer In: 1930

Baldwin, WI 54002 Unit #: 503535

Cellular 612-812-6584 VIN #: 1FDWE4FK1 NDC37121

00 0.12 0.12 000 .				VIIV # . II DWL-II KI NDOO! IZI	
Part Description	Qty	Sale	Ext	Labor Description	Ext
Fuse tap	2.000	8.25	16.50	   Work Requested: Install VEDR camera system, FAI	n/c
Fuse Min 25	2.000	1.00	2.00	Labor	220.00
Job Supplies			15.250	Install owner provided VEDR camera system. Had to remove headliner to install. Reverse camera on constant, wire into key on source.	
				Inspection Vehicle Inspection & PASSED	85.00

340.11 Revisions 0.00 Current Estimate 340.11 Org. Estimate

305.00 Labor: Parts: 33.75

SubTotal: Tax:

338.75 1.36

Total:

340.11 \$340.11

Bal Due:

Vehicle Received: 5/15/2023

[ Payments - ]

Customer Number: 16

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com