

Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231597

INVOICE

Ref # : 5499

Printed Date: 04/28/2023

Work Completed: 04/27/2023

Kath Fuel Oil Service Co. - Paul Ruedy

3096 Rice Street
Saint Paul, MN 55113
Office 651-484-3325

2020 Peterbilt - 567 - Paccar MX-13 PCI 6 CYL

Lic # : PAN8129

Odometer In : 162157

Unit # : 5499

VIN # : 1XPCDP9X0 LD665499

Part Description	Qty	Sale	Ext	Labor Description	Ext
Filter Oil	1.000	91.72	91.72	Work Requested: PM	n/c
Oil Filter	1.000	71.88	71.88	PM Service	100.00
Filter Fuel	1.000	47.40	47.40	Change oil, oil and fuel filters, lube vehicle. Used 44 quarts of Kath supplied oil. Replace owner provided air dryer filter.	
Fuel Filter	1.000	97.28	97.28	Diagnostics	50.00
Job Supplies			10.250	Engine/transmission/ABS/vehicle Diagnostics	
				Labor	55.00
				Scan for ABS codes, inactive code for ABS timeout present. No repairs needed unless code active, possible wiring issues, advise if codes return.	
				[Recommendations]	
				SAI due by 8/31/2023	
				PM due by 10/27/2023 or 180,157 miles to extend the life of your vehicle.	

Org. Estimate 546.73 Revisions 0.00 Current Estimate 546.73

Labor:	205.00
Parts:	318.53
SubTotal:	523.53
Tax:	23.20
Total:	546.73
Bal Due:	\$546.73

[Payments -]

Vehicle Received: 4/27/2023

Customer Number : 105

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com