

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231914**

**INVOICE**

Ref # : 82907

Printed Date: 05/19/2023

Work Completed: 05/18/2023

**Butch Trucking - Jack Hetrick**  
 4911 170th Lane NW  
 Andover, MN 55304  
 Cellular 612-309-6860 Jack Hetrick

2005 Freightliner - Van Chassis - MT-55 - Cummins ISB CM850 6 CYL  
 Lic # : YVA8532 Odometer In : 279958  
 Unit # : 82907  
 VIN # : 4UZAARBW3 5CN85889

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	16.000	4.45	71.20	Work Requested: PM, Fix rear bumper rubber.	n/c
Filter Oil	1.000	19.09	19.09	PM Service	80.00
Filter Fuel	1.000	27.75	27.75	Change oil, oil and fuel filters, lube vehicle	
Filter Fuel	1.000	52.44	52.44	Labor	55.00
255/70R/22.5 Steer	1.000	353.58	353.58	Inspect rear bumper, fasten loose rubber bumpers back in place.	
Tire Disposal	1.000	15.00	15.00	Labor tire	80.00
255/70/22.5 Steer Mahtomedi	1.000	353.45	353.45	Replace steer tires and balance, air to 100 PSI. Existing tires were at 0 & 1/32"	
Tire Disposal	1.000	15.00	15.00		
Job Supplies			10.750		

**[ Recommendations ]**

FAI due by 6/30/2023  
 PM due by 11/18/2023 or 287,958 miles to extend the life of your vehicle.  
 Maintenance interval due 8/18/2023 to your vehicle.  
 Transmission cooler line on radiator leaking.

Org. Estimate 1,197.98 Revisions 0.00 Current Estimate 1,197.98

<b>Labor:</b>	<b>215.00</b>
<b>Parts:</b>	<b>888.26</b>
<b>Tire Fees:</b>	<b>30.000</b>
<b>SubTotal:</b>	<b>1,133.26</b>
<b>Tax:</b>	<b>64.72</b>
<b>Total:</b>	<b>1,197.98</b>
<b>Bal Due:</b>	<b>\$1,197.98</b>

[ Payments - ]

Vehicle Received: 5/18/2023

Customer Number : 8

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)