

**Job Site Repair LLC**  
12015 Brockton Ln N  
Maple Grove, MN. 55369  
Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**225370**

**INVOICE**

Ref # : 98703

Printed Date: 12/25/2022

Work Completed: 12/22/2022

**Groundforce, Inc. - Gayle Gammel**  
472 Springhill Road  
Vadnais Heights, MN 55127  
Cellular 651-402-5977

2003 International - 1000 Series - 1652 SC - International T 444E Diam  
Lic # : YAX4625 Odometer In : 292992  
Unit # : 98703  
VIN # : 4KAMGABM7 3A948177

Part Description	Qty	Sale	Ext	Labor Description	Ext
Battery	2.000	118.71	237.42	Work Requested: Check batteries	n/c
Job Supplies			5.500	Labor	110.00
				Charge and test batteries, fails testing. Replace batteries, clean and tighten connections. Alternator output at 86 amps under load, weak, may need replacement soon, parasitic draw under 1 amp.	
				<b>[ Recommendations ]</b> FAI due by 11/30/2023	

Org. Estimate 370.43 Revisions 0.00 Current Estimate 370.43

<b>Labor:</b>	<b>110.00</b>
<b>Parts:</b>	<b>242.92</b>
<b>SubTotal:</b>	<b>352.92</b>
<b>Tax:</b>	<b>17.51</b>
<b>Total:</b>	<b>370.43</b>
<b>Bal Due:</b>	<b>\$370.43</b>

[ Payments - ]

Vehicle Received: 12/22/2022

Customer Number : 21

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)