

**Job Site Repair LLC**  
12015 Brockton Ln N  
Maple Grove, MN. 55369  
Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231722**

**INVOICE**

Ref # : 503153

Printed Date: 05/09/2023

Work Completed: 05/05/2023

**Fern, Inc. - Darla Fern**  
1325 200th Street  
Baldwin, WI 54002  
Cellular 612-812-6584

2022 Freightliner - Van Chassis - MT-45 - Power Solutions International

Lic # :

Odometer In : 596

Unit # : 503153

VIN # :

Part Description	Qty	Sale	Ext	Labor Description	Ext
Headlight	1.000	17.24	17.24	Work Requested: Inspect lights	n/c
Job Supplies			1.380	Labor	27.50
				Inspect lights, replace burnt out drivers side headlight. All lights work properly after repairs.	

Org. Estimate 47.39 Revisions 0.00 Current Estimate 47.39

<b>Labor:</b>	<b>27.50</b>
<b>Parts:</b>	<b>18.62</b>
<b>SubTotal:</b>	<b>46.12</b>
<b>Tax:</b>	<b>1.27</b>
<b>Total:</b>	<b>47.39</b>
<b>Bal Due:</b>	<b>\$47.39</b>

[ Payments - ]

Vehicle Received: 5/5/2023

Customer Number : 16

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)