

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231859**

**INVOICE**

Ref # : 312312

Printed Date: 05/17/2023

Work Completed: 05/15/2023

**Midwest Deliveries, Inc. - Ryan Brunette**  
 489 Omaha Road  
 Hudson, WI 54016  
 Cellular 651-775-7381

2014 Ford - F59 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL  
 Lic # : FB38179 Odometer In : 189902  
 Unit # : 312312  
 VIN # : 1F66F5KY1 E0A02746

Part Description	Qty	Sale	Ext	Labor Description	Ext
Job Supplies			3.940	Work Requested: Brakes noisy, steering loose.	n/c
				Labor	n/c
				Inspect brakes all pads over 10 MM thick, rotors fine and calipers move freely.	
				Labor	78.75
				Inspect for cause of loose steering, found play in pitman arm, align and tighten down. Test drive, steering tight after repairs.	
				<b>[ Recommendations ]</b>	
				FAI due by 1/31/2024	
				PM due by 6/3/2023 or 181,392 miles to extend the life of your vehicle.	

Org. Estimate 82.69      Revisions 0.00      Current Estimate 82.69

<b>Labor:</b>	<b>78.75</b>
<b>Parts:</b>	<b>3.94</b>
<b>SubTotal:</b>	<b>82.69</b>
<b>Tax:</b>	<b>0.00</b>
<b>Total:</b>	<b>82.69</b>
<b>Bal Due:</b>	<b>\$82.69</b>

[ Payments - ]

Vehicle Received: 5/15/2023

Customer Number : 61

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)