

Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231591

Org. Est. # 013402

INVOICE

Ref # : 324979

Printed Date: 04/28/2023

Work Completed: 04/27/2023

AZAL, Inc. - Ali Aldera
7317 W Franklin Ave.
St. Louis Park, MN 55426
Office 612-803-1511 Ali Aldera
Cellular 651-666-3354 Ryan Fritz

2017 Freightliner - Van Chassis - MT-55 - Cummins ISB6.7 CM2350 6 (
Lic # : YBR3605 Odometer In : 171606
Unit # : 324979
VIN # : 4UZAARDU7 HCHW8487

Part Description	Qty	Sale	Ext	Labor Description	Ext
Whiting Security J latch	1.000	325.78	325.78	Work Requested: Rear door Enforcer lock pocket	n/c
Rivets 1/4	8.000	0.72	5.76	coming off.	
Job Supplies			11.000	Labor	220.00
				Inspect rear door Enforcer lock box, found damaged, remove existing and weld in new pocket. Replace worn out J-hook assembly, rivet in place. Lube and adjust door, door works fine after repairs.	
				[Recommendations]	
				PM due by 8/3/2023 or 175,000 miles to extend the life of your vehicle.	
				FAI due by 5/31/2023	

Org. Estimate 587.49 Revisions 0.00 Current Estimate 587.49

Labor:	220.00
Parts:	342.54
SubTotal:	562.54
Tax:	24.95
Total:	587.49
Bal Due:	\$587.49

[Payments -]

Vehicle Received: 4/27/2023

Customer Number : 4

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com