Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231712

Odometer In: 59499

INVOICE Work Completed: 05/04/2023 Ref #: 423608 Printed Date: 05/08/2023

Hawkeye Delivery, Inc. - Joe Broich

2020 Freightliner - Van Chassis - MT-55 - General Motors 6.0L L96 - Va

2401 Friendship Lane

Lic #: YCA2806

Unit #: 423608

Burnsville, MN 55337 Cellular 612-910-2971 Joe

VIN #: 4UZAC3EAX LCLU7588

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	6.000	4.45	26.70	Work Requested: PM	n/c
Oil Filter	1.000	8.13	8.13	PM Service	80.00
Grommet super 40	2.000	1.76	3.52	Change oil, oil filter, lube vehicle	
245/70/19.5 DC RT600 Rogers	2.000	251.55	503.10	Labor	55.00
Tire Disposal	2.000	15.00	30.00	Inspect lights, convert reverse lights to grommet style, reuse lights.	
245/70R/19.5 HMT Deep XT	4.000	204.13	816.52	All lights work properly after repairs.	
Tire Disposal	4.000	15.00	60.00	Labor tire	80.00
Job Supplies			16.750	Replace steer tires and balance, air to 100 PSI	
				Labor tire	120.00
				Replace drive tires, air to 100 PSI.	

[Recommendations]

PM due by 9/4/2023 or 63,499 miles to extend the life of your

vehicle.

FAI due by 6/30/2023

1,901.91 Revisions 0.00 Current Estimate 1,901.91 Org. Estimate

335.00 Labor: Parts: 1,374.72

Tire Fees:

90.000

SubTotal: Tax:

1,799.72 102.19

Total: Bal Due:

1,901.91 \$1,901.91

[Payments -]

Vehicle Received: 5/4/2023 Customer Number: 22

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair

Visit us on the web: www.jobsiterepair.com