Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231767

INVOICE

Ref #: 425100

Printed Date: 05/11/2023

2019 Ford - F59/F53 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

Work Completed: 05/09/2023

North Star Courier - Mitch Boeder

7347 Sping Lake Road

Lic #: YBY1004

Odometer In: 72279

Saint Paul, MN 55112 Cellular 507-351-5599

Unit #: 425100

VIN #: 1F66F5KYX K0A17547

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	7.500	4.45	33.38	Work Requested: PM, replace tires	n/c
Filter oil	1.000	8.46	8.46	PM Service	80.00
Antifreeze Dex Cool	4.000	4.09	16.36	Change oil, oil filter, lube vehicle	
W/ Washer Fluid	1.000	3.39	3.39	Labor	27.50
W/wiper blade	2.000	10.53	21.06	Replace worn wiper blades	
245/70/19.5 DC RT600 Rogers	2.000	251.55	503.10	Labor tire	80.00
Tire Disposal	2.000	15.00	30.00	Replace steer tires and balance, air to 100 PSI	
245/70R/19.5 HMT Deep XT	4.000	204.13	816.52	Labor tire	120.00
Tire Disposal	4.000	15.00	60.00	Replace drive tires, air to 100 PSI.	
Job Supplies			15.380		

[Recommendations]

PM due by 9/9/2023 or 76,279 miles to extend the life of your vehicle.

FAI due by 10/31/2023

1,898.03 Revisions 0.00 Current Estimate 1,898.03 Org. Estimate

307.50 Labor: Parts: 1,417.65

Tire Fees:

90.000

SubTotal: Tax:

1,815.15 105.52 1,920.67

Total: Bal Due:

\$1,920.67

[Payments -]

Vehicle Received: 5/9/2023 Customer Number: 81

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com