Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231972

Odometer In: 65412

Work Completed: 05/22/2023

INVOICE Ref #: 447572 Printed Date: 05/23/2023

2021 Ford - E Series - E450 - Ford 7.3L 99K 8 CYL Refyn, Inc. - Bhargav Kachhadiya

433 S. 7th Street Apt 1709 Lic #: 35-395D Minneapolis, MN 55415 Unit #: 447572

Home 224-607-7778

VIN #: 1FC3E4KK8 MDC29738 Sale **Part Description** Qty Ext **Labor Description** Ext Tire Disposal Fee 1.000 15.00 15.00 Work Requested: Left front tire leaking n/c Job Supplies 2.000 Labor tire 40.00

> Replace drivers side steer tire and balance, air to 100 PSI. Puncture in tire was not able to be repaired, used customer owned run out tire at 10/32" for replacement.

[Recommendations]

PM due by 9/18/2023 or 68,749 miles to extend the life of your vehicle.

FAI due by 12/31/2023

57.00 Revisions 0.00 Current Estimate 57.00 Org. Estimate

Labor: 40.00 Parts: 17.00

SubTotal: Tax: Total:

57.00 0.00 57.00

Bal Due:

\$57.00

[Payments -]

Vehicle Received: 5/22/2023 Customer Number: 108

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair

Visit us on the web: www.jobsiterepair.com