

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**230241**

**INVOICE**

Ref # : 99639

Printed Date: 01/20/2023

Work Completed: 01/18/2023

**Groundforce, Inc. - Gayle Gammel**  
 472 Springhill Road  
 Vadnais Heights, MN 55127  
 Cellular 651-402-5977

2004 Freightliner - Van Chassis - MT-45 - Mercedes-Benz MBE 900 EP  
 Lic # : YBD4023 Odometer In : 351799  
 Unit # : 99639  
 VIN # : 4UZAAPCP7 4CM98877

Part Description	Qty	Sale	Ext	Labor Description	Ext
Hanger Tail pipe	1.000	5.71	5.71	Work Requested: Exhaust pipe broken off	n/c
Exhaust Pipe	1.000	353.81	353.81	Labor	165.00
Clamp exhaust	1.000	12.01	12.01	Inspect exhaust system, replace bent up exhaust tailpipe, hanger and clamps. Exhaust complete after repairs/	
Muffler clamp	1.000	10.67	10.67		
Job Supplies			8.250		

**[ Recommendations ]**

PM due by 2/19/2022 or 357262 miles to extend the life of your vehicle.  
 FAI due by 8/31/2023  
 Maintenance interval due 11/19/2021 to your vehicle.

Org. Estimate 554.77 Revisions 0.00 Current Estimate 554.77

<b>Labor:</b>	<b>165.00</b>
<b>Parts:</b>	<b>390.45</b>
<b>SubTotal:</b>	<b>555.45</b>
<b>Tax:</b>	<b>28.19</b>
<b>Total:</b>	<b>583.64</b>
<b>Bal Due:</b>	<b>\$583.64</b>

[ Payments - ]

Vehicle Received: 1/18/2023

Customer Number : 21

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)