

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231915**

**INVOICE**

Ref # : 325589

Printed Date: 05/19/2023

Work Completed: 05/18/2023

**Fern, Inc. - Darla Fern**  
 1325 200th Street  
 Baldwin, WI 54002  
 Cellular 612-812-6584

2017 Freightliner - Van Chassis - MT-55 - Cummins ISB6.7 CM2350 6 C  
 Lic # : GD72584 Odometer In : 116831  
 Unit # : 325589  
 VIN # : 4UZAARDU9 HCHW8491

Part Description	Qty	Sale	Ext	Labor Description	Ext
Job Supplies			4.130	Work Requested: Rear door won't open Labor	n/c 82.50
				Inspect rear door, found Enforcer lock jammed up, get door open and clean dirt from lock pocket. Remove key and lube lock cylinder. Door works freely after repairs.	
				<b>[ Recommendations ]</b> FAI due by 6/30/2023 PM due by 10/27/2023 or 124,634 miles to extend the life of your vehicle. Maintenance interval due 7/27/2023 to your vehicle.	

Org. Estimate 86.63      Revisions 0.00      Current Estimate 86.63

<b>Labor:</b>	<b>82.50</b>
<b>Parts:</b>	<b>4.13</b>
<b>SubTotal:</b>	<b>86.63</b>
<b>Tax:</b>	<b>0.00</b>
<b>Total:</b>	<b>86.63</b>
<b>Bal Due:</b>	<b>\$86.63</b>

[ Payments - ]

Vehicle Received: 5/18/2023

Customer Number : 16

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)