

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
61993300	402639
DATE 12-20-22	

MOTOR CARRIER OPERATOR
Fedex ground

ADDRESS
1000 Fedex drive

CITY, STATE, ZIP CODE
Pittsburgh PA 15108

VEHICLE TYPE TRACTOR TRAILER TRUCK BUS
 (OTHER) *van*

INSPECTOR'S NAME (PRINT OR TYPE)
Andrew Kuelborg

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.
 YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE) LIC. PLATE NO. VIN OTHER
4UZAC3EA4HCE1153

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING	
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).	
✓			b. Parking Brake System	✓			b. Front End Structure				13. WINDSHIELD WIPERS	
✓			c. Brake Drums or Rotors	✓			c. Intermodal Container Securement Devices	✓			No missing, damaged, or inoperable wipers.	
✓			d. Brake Hose	✓			7. STEERING MECHANISM				14. MOTORCOACH SEATS	
✓			e. Brake Tubing	NA			a. Steering Wheel Free Play	NA			Seats securely fastened to the vehicle structure.	
✓			f. Low Pressure Warning Device	✓			b. Steering Column	✓			15. REAR IMPACT GUARD	
✓			g. Tractor Protection Valve	✓			c. Front Axle Beam/All Other Steering Components	✓			In place, securely attached, proper size, proper placement (see 393.86).	
✓			h. Air Compressor	✓			d. Steering Gear Box	✓			16. OTHER	
✓			i. Electric Brakes	✓			e. Pitman Arm	✓			List any other condition(s) which may prevent safe operation of this vehicle.	
✓			j. Hydraulic Brakes	✓			f. Power Steering	✓				
✓			k. Vacuum Systems	✓			g. Ball and Socket Joints					
✓			l. Antilock Brake System	✓			h. Tie Rods and Drag Links					
✓			m. Automatic Brake Adjusters	✓			i. Nuts					
✓			2. COUPLING DEVICES					j. Steering System				
✓			a. Fifth Wheels	✓			8. SUSPENSION					
✓			b. Pintle Hooks	✓			a. Axle Positioning Parts					
✓			c. Drawbar/Towbar Eye	✓			b. Spring Assembly					
✓			d. Drawbar/Towbar Tongue	✓			c. Torque, Radius or Tracking Components					
✓			e. Safety Devices	✓			9. FRAME					
✓			f. Saddle-Mounts	✓			a. Frame Members					
✓			3. EXHAUST SYSTEM					b. Tire and Wheel Clearance				
✓			a. No leaks forward of/ directly below the driver/ sleeper compartment.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)					
NA			b. Bus: No leaking/ discharging in violation of standard.	✓			10. TIRES					
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	NA			a. Steer-Axle Tires					
✓			4. FUEL SYSTEM					b. All Other Tires				
✓			a. No visible leak.	✓			c. Speed-Restricted Tires					
✓			b. Fuel Tank Filler Cap	NA			11. WHEELS AND RIMS					
✓			c. Fuel tank securely attached.	✓			a. Lock or Side Ring					
✓			5. LIGHTING DEVICES					b. Wheels and Rims				
✓			All required lights/reflectors operable.	✓			c. Fasteners					
✓				✓			d. Welds					

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.