

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

230652

INVOICE

Ref # : 404280

Printed Date: 02/23/2023

Work Completed: 02/15/2023

JR Delivery, Inc. - Jeff Russ

685 Forest Road
 Big Lake, MN 55309
 Cellular 763-443-9654

2017 Ford - F59 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

Lic # : YBU5723

Odometer In : 151743

Unit # : 404280

VIN # : 1F66F5KY5 H0A17786

Part Description	Qty	Sale	Ext	Labor Description	Ext
Amber LED 3/4 penny light	1.000	23.24	23.24	Work Requested: Inspect lights	n/c
Job Supplies			4.130	Labor	82.50
				Inspect lights, hood light on passenger side dim, If wiggle wiring it would go out. Inspect wiring harness and found faulty ground wire, repair connection and replace light. All lights work properly after repairs.	
				[Recommendations]	
				FAI due by 5/31/2023	
				PM due by 4/12/2023 or 150,413 miles to extend the life of your vehicle.	

Org. Estimate 111.62 Revisions 0.00 Current Estimate 111.62

Labor:	82.50
Parts:	27.37
SubTotal:	109.87
Tax:	1.75
Total:	111.62
Bal Due:	\$111.62

[Payments -]

Vehicle Received: 2/15/2023

Customer Number : 87

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com