

Job Site Repair LLC

12015 Brockton Ln N

Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE**231900****INVOICE**

Ref #: 404280

Printed Date: 05/19/2023

Work Completed: 05/17/2023**JR Delivery, Inc. - Jeff Russ**

685 Forest Road

Big Lake, MN 55309

Cellular 763-443-9654

2017 Ford - F59 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

Lic # : YBU5723

Odometer In : 158591

Unit # : 404280

VIN # : 1F66F5KY5 H0A17786

Part Description	Qty	Sale	Ext	Labor Description	Ext
------------------	-----	------	-----	-------------------	-----

Work Requested: Federal Annual Inspection

n/c

Inspection

85.00

Vehicle Inspection & PASSED

[Recommendations]

FAI due by 5/31/2024

PM due by 7/22/2023 or 158,776 miles to extend the life of your vehicle.

Org. Estimate	85.00	Revisions	0.00	Current Estimate	85.00
---------------	-------	-----------	------	------------------	-------

Labor: 85.00**Parts: 0.00****SubTotal: 85.00****Tax: 0.00****Total: 85.00****Bal Due: \$85.00**

[Payments -]

Vehicle Received: 5/17/2023

Customer Number : 87

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.comEmail Address: jeff@jobsiterepair.com