

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231955

INVOICE

Ref # : 426272

Printed Date: 05/22/2023

Work Completed: 05/19/2023

VP Transport - Parth Lparel

7161 Pleasant View Drive
 Saint Paul, MN 55112
 Cellular 651-206-8345

2019 Ford - F59/F53 Stripped Chassis - Ford 6.8L 99Y F59 10 CYL

Lic # : YBY0992

Odometer In : 83358

Unit # : 426272

VIN # : 1F66F5KY1 **K0A11961**

Part Description	Qty	Sale	Ext	Labor Description	Ext
------------------	-----	------	-----	-------------------	-----

Work Requested: Federal Annual Inspection	n/c
Inspection	85.00
Vehicle Inspection & PASSED	

[Recommendations]

PM due by 7/20/2023 or 83,757 miles to extend the life of your vehicle.
 FAI due by 5/31/2024

Org. Estimate	85.00	Revisions	0.00	Current Estimate	85.00
---------------	-------	-----------	------	------------------	-------

Labor:	85.00
Parts:	0.00
<hr/>	
SubTotal:	85.00
Tax:	0.00
Total:	85.00
Bal Due:	\$85.00

[Payments -]

Vehicle Received: 5/19/2023

Customer Number : 89

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com