

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231640**

**INVOICE**

Ref # : 429170

Printed Date: 05/04/2023

Work Completed: 05/01/2023

**AZAL, Inc. - Ali Aldera**  
 7317 W Franklin Ave.  
 St. Louis Park, MN 55426  
 Office 612-803-1511 Ali Aldera  
 Cellular 651-666-3354 Ryan Fritz

2020 Freightliner - Van Chassis - MT-45 - General Motors 6.0L L96 - Va  
 Lic # : YBY7382 Odometer In : 68790  
 Unit # : 429170  
 VIN # : 4UZAC2EA5 LCLX0531

Part Description	Qty	Sale	Ext	Labor Description	Ext
Alarm Back up	1.000	46.82	46.82	Work Requested: Back up alarm not working	n/c
Job Supplies			2.750	Labor	55.00
				Inspect backup alarm system, found alarm burnt out, replace alarm. Backup alarm system works normally after repairs.	
				<b>[ Recommendations ]</b>	
				PM due by 8/24/2023 or 72,219 miles to extend the life of your vehicle.	
				FAI due by 4/30/2024	

Org. Estimate 108.09      Revisions 0.00      Current Estimate 108.09

<b>Labor:</b>	<b>55.00</b>
<b>Parts:</b>	<b>49.57</b>
<b>SubTotal:</b>	<b>104.57</b>
<b>Tax:</b>	<b>3.52</b>
<b>Total:</b>	<b>108.09</b>
<b>Bal Due:</b>	<b>\$108.09</b>

[ Payments - ]

Vehicle Received: 5/1/2023

Customer Number : 4

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)