

ANNUAL VEHICLE INSPECTION REPORT

| VEHICLE HISTORY RECORD | |
|--|-------------------|
| REPORT NUMBER | FLEET UNIT NUMBER |
| 59017456 | 432418 |
| DATE 8-1-22 | |

| | |
|--|---|
| MOTOR CARRIER OPERATOR <p style="font-size: 1.2em; text-align: center;">Fedex ground</p> ADDRESS <p style="font-size: 1.2em; text-align: center;">1000 Fedex drive</p> CITY, STATE, ZIP CODE <p style="font-size: 1.2em; text-align: center;">Pittsburgh PA 15108</p> VEHICLE TYPE <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input checked="" type="checkbox"/> (OTHER) Van | INSPECTOR'S NAME (PRINT OR TYPE) <p style="font-size: 1.2em; text-align: center;">Andrew Keelbores</p> THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES |
| VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER <p style="font-size: 1.2em; text-align: center;">1HA3GTCLGXLN006779</p> INSPECTION AGENCY LOCATION (OPTIONAL) | |

| VEHICLE COMPONENTS INSPECTED | | | | | | | | | | | |
|------------------------------|--------------|---------------|---|----|--------------|---------------|--|----|---|--|---|
| OK | NEEDS REPAIR | REPAIRED DATE | ITEM | OK | NEEDS REPAIR | REPAIRED DATE | ITEM | OK | NEEDS REPAIR | REPAIRED DATE | ITEM |
| | | | 1. BRAKE SYSTEM | | | | 6. SAFE LOADING | | | | 10. TIRES |
| ✓ | | | a. Service Brakes | ✓ | | | a. Part(s) of vehicle or condition of loading such that the spare tire or any part of the load or dunnage can fall onto the roadway. | ✓ | | | a. Tires on any steering axle of a power unit. |
| ✓ | | | b. Parking Brake System | ✓ | | | b. Protection against shifting cargo. | ✓ | | | b. All other tires. |
| ✓ | | | c. Brake Drums or Rotors | ✓ | | | c. Container securement devices on intermodal equipment. | NA | | | c. Installation of speed-restricted tires unless specifically designated by motor carrier. |
| ✓ | | | d. Brake Hose | ✓ | | | | NA | | | |
| ✓ | | | e. Brake Tubing | ✓ | | | | NA | | | |
| ✓ | | | f. Low Pressure Warning Device | ✓ | | | | NA | | | |
| ✓ | | | g. Tractor Protection Valve | NA | | | | NA | | | |
| ✓ | | | h. Air Compressor | NA | | | | NA | | | |
| ✓ | | | i. Electric Brakes | ✓ | | | | ✓ | | | |
| ✓ | | | j. Hydraulic Brakes | ✓ | | | | ✓ | | | |
| ✓ | | | k. Vacuum Systems | ✓ | | | | ✓ | | | |
| ✓ | | | l. Antilock Brake System | ✓ | | | | ✓ | | | |
| ✓ | | | m. Automatic Brake Adjusters | ✓ | | | | ✓ | | | |
| | | | 2. COUPLING DEVICES | | | | 7. STEERING MECHANISM | | | | 11. WHEELS AND RIMS |
| ✓ | | | a. Fifth Wheels | ✓ | | | a. Steering Wheel Free Play | ✓ | | | a. Lock or Side Ring |
| ✓ | | | b. Pintle Hooks | ✓ | | | b. Steering Column | ✓ | | | b. Wheels and Rims |
| ✓ | | | c. Drawbar/Towbar Eye | ✓ | | | c. Front Axle Beam and All Steering Components Other Than Steering Column | ✓ | | | c. Fasteners |
| ✓ | | | d. Drawbar/Towbar Tongue | ✓ | | | d. Steering Gear Box | ✓ | | | d. Welds |
| ✓ | | | e. Safety Devices | ✓ | | | e. Pitman Arm | ✓ | | | |
| ✓ | | | f. Saddle-Mounts | ✓ | | | f. Power Steering | ✓ | | | |
| | | | 3. EXHAUST SYSTEM | | | | 8. SUSPENSION | | | | 12. WINDSHIELD GLAZING |
| ✓ | | | a. Exhaust system leaking forward of or directly below the driver/sleeper compartment. | ✓ | | | a. Any U-bolt(s), spring hanger(s), or other axle positioning part(s) cracked, broken, loose or missing resulting in shifting of an axle from its normal position. | ✓ | | | Requirements and exceptions as stated pertaining to any crack, discoloration or vision reducing matter (reference 393.60 for exceptions). |
| NA | | | b. Bus exhaust system leaking or discharging in violation of standard. | ✓ | | | b. Spring Assembly | ✓ | | | |
| ✓ | | | c. Exhaust system likely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of the motor vehicle. | ✓ | | | c. Torque, Radius or Tracking Components | ✓ | | | |
| | | | 4. FUEL SYSTEM | | | | 9. FRAME | | | | 13. WINDSHIELD WIPERS |
| ✓ | | | a. Visible leak. | ✓ | | | a. Frame Members | ✓ | | | Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective. |
| ✓ | | | b. Fuel tank filler cap missing. | ✓ | | | b. Tire and Wheel Clearance | ✓ | | | |
| ✓ | | | c. Fuel tank securely attached. | ✓ | | | c. Adjustable Axle Assemblies (Sliding Subframes) | ✓ | | | |
| | | | 5. LIGHTING DEVICES | | | | | | | 14. MOTORCOACH SEATS | |
| ✓ | | | All lighting devices and reflectors required by Part 393 shall be operable. | NA | | | | | | Any passenger seat that is not securely fastened to the vehicle structure. | |
| | | | | | | | | | 15. OTHER | | |
| | | | | | | | | | List any other condition(s) which may prevent safe operation of this vehicle. | | |

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.