

**Job Site Repair LLC**  
12015 Brockton Ln N  
Maple Grove, MN. 55369  
Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231794**

**INVOICE**

Ref # : 433503

Printed Date: 05/12/2023

Work Completed: 05/11/2023

**Midwest Deliveries, Inc. - Ryan Brunette**

489 Omaha Road  
Hudson, WI 54016  
Cellular 651-775-7381

2020 Freightliner - Van Chassis - MT-45 - Cummins B6.7 CM2350 B121

Lic # : PLB4732

Odometer In : 94306

Unit # : 433503

VIN # : 4UZAAPFD8 LCMD7033

Part Description	Qty	Sale	Ext	Labor Description	Ext
Switch brake	1.000	68.03	68.03	Work Requested: Brake light switch broken	n/c
Job Supplies			2.630	Labor	52.50
				Replace faulty brake light switch	

**[ Recommendations ]**

PM due by 9/27/2023 or 98,148 miles to extend the life of your vehicle.

FAI due by 1/31/2024

Maintenance interval due 6/27/2023 to your vehicle.

Org. Estimate 128.18 Revisions 0.00 Current Estimate 128.18

<b>Labor:</b>	<b>52.50</b>
<b>Parts:</b>	<b>70.66</b>
<b>SubTotal:</b>	<b>123.16</b>
<b>Tax:</b>	<b>5.02</b>
<b>Total:</b>	<b>128.18</b>
<b>Bal Due:</b>	<b>\$128.18</b>

[ Payments - ]

Vehicle Received: 5/11/2023

Customer Number : 61

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)