Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231901

INVOICE Work Completed: 05/17/2023 Ref #: 433547 Printed Date: 05/19/2023 2020 Ford - F59 Stripped Chassis - Ford 7.3L 99N 8 CYL JR Delivery, Inc. - Jeff Russ 685 Forest Road Lic #: YBZ2525 Odometer In: 69462 Big Lake, MN 55309 Unit #: 433547 Cellular 763-443-9654 VIN #: 1F66F5KN4 L0A03182 Qty Sale **Part Description Labor Description** Ext Work Requested: Federal Annual Inspection n/c Inspection 85.00 Vehicle Inspection & PASSED [Recommendations] FAI due by 5/31/2024 PM due by 8/18/2023 or 71,230 miles to extend the life of your vehicle. 85.00 Revisions 0.00 Current Estimate 85.00 Org. Estimate Labor: 85.00 Parts: 0.00 SubTotal: 85.00 Tax: 0.00 Total: 85.00 Bal Due: \$85.00 [Payments -] Vehicle Received: 5/17/2023 Customer Number: 87

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the