## Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231846

Odometer In: 217824

INVOICE Ref #: 436568 Printed Date: 05/16/2023 Work Completed: 05/15/2023

Lake View Delivery, Inc. - Nathan Wegener

2013 Freightliner - Van Chassis - MT-55 - Cummins ISB6.7 CM2250 6 (

2812 Maryland Ave. S. Minneapolis, MN 55426

Lic #: YBY4085 Unit #: 436568

Cellular 612-817-6566

VIN #: 4UZAARDU5 DCFK9563

**Part Description** Qty Sale Ext **Labor Description** Ext Parking Brake Switch 1.000 37.31 37.31 Work Requested: Park brake alarm on constantly n/c Job Supplies 5.500 Labor 110.00

Inspect park brake alarm system, found park brake switch broken and mounting damaged. Replace switch and repair mounting bracket and adjust. Park brake alrm works normally after repairs.

## [ Recommendations ]

PM due by 8/23/2023 or 220,837 miles to extend the life of your vehicle.

FAI due by 7/31/2023

Maintenance interval due 5/23/2023 to your vehicle.

Org. Estimate 155.62 Revisions 0.00 Current Estimate 155.62

Labor: 110.00 Parts: 42.81

SubTotal: Tax: 152.81 2.81 155.62

Total: Bal Due:

155.62 \$155.62

[ Payments - ]

Vehicle Received: 5/15/2023 Customer Number : 79

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com