

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
58288272	441321
DATE 10-19-2022	

MOTOR CARRIER OPERATOR fed ex ground ADDRESS 1000 fed ex drive CITY, STATE, ZIP CODE Pittsburgh PA 15108 VEHICLE TYPE <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input checked="" type="checkbox"/> (OTHER) Van	INSPECTOR'S NAME (PRINT OR TYPE) Will Thorsen THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER IFDWE3FK1MD C09103 INSPECTION AGENCY/LOCATION (OPTIONAL)
---	--

VEHICLE COMPONENTS INSPECTED												
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING	
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).	
✓			b. Parking Brake System	✓			b. Front End Structure	✓			13. WINDSHIELD WIPERS	
✓			c. Brake Drums or Rotors	✓			c. Intermodal Container Securement Devices	✓			No missing, damaged, or inoperable wipers.	
✓			d. Brake Hose	✓			7. STEERING MECHANISM			14. MOTORCOACH SEATS		
✓			e. Brake Tubing	✓			a. Steering Wheel Free Play	✓			Seats securely fastened to the vehicle structure.	
✓			f. Low Pressure Warning Device	✓			b. Steering Column	✓			15. REAR IMPACT GUARD	
✓			g. Tractor Protection Valve	✓			c. Front Axle Beam/All Other Steering Components	✓			In place, securely attached, proper size, proper placement (see 393.86).	
✓			h. Air Compressor	✓			d. Steering Gear Box	✓			16. OTHER	
✓			i. Electric Brakes	✓			e. Pitman Arm	✓			List any other condition(s) which may prevent safe operation of this vehicle.	
✓			j. Hydraulic Brakes	✓			f. Power Steering	✓				
✓			k. Vacuum Systems	✓			g. Ball and Socket Joints	✓				
✓			l. Antilock Brake System	✓			h. Tie Rods and Drag Links	✓				
✓			m. Automatic Brake Adjusters	✓			i. Nuts	✓				
✓			2. COUPLING DEVICES			✓		j. Steering System	✓			
✓			a. Fifth Wheels	✓			8. SUSPENSION					
✓			b. Pintle Hooks	✓			a. Axle Positioning Parts					
✓			c. Drawbar/Towbar Eye	✓			b. Spring Assembly					
✓			d. Drawbar/Towbar Tongue	✓			c. Torque, Radius or Tracking Components					
✓			e. Safety Devices	✓			9. FRAME					
✓			f. Saddle-Mounts	✓			a. Frame Members					
✓			3. EXHAUST SYSTEM			✓		b. Tire and Wheel Clearance				
✓			a. No leaks forward of/ directly below the driver/ sleeper compartment.	✓			c. Adjustable Axle Assemblies (Sliding Subframes)					
✓			b. Bus: No leaking/ discharging in violation of standard.	✓			10. TIRES					
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			a. Steer-Axle Tires					
✓			4. FUEL SYSTEM			✓		b. All Other Tires				
✓			a. No visible leak.	✓			c. Speed-Restricted Tires					
✓			b. Fuel Tank Filler Cap	✓			11. WHEELS AND RIMS					
✓			c. Fuel tank securely attached.	✓			a. Lock or Side Ring					
✓			5. LIGHTING DEVICES			✓		b. Wheels and Rims				
✓			All required lights/reflectors operable.	✓			c. Fasteners					
✓				✓			d. Welds					

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.