

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231560

INVOICE

Ref # : 444040

Printed Date: 04/26/2023

Work Completed: 01/01/-4713

AZAL, Inc. - Ali Aldera
 7317 W Franklin Ave.
 St. Louis Park, MN 55426
 Office 612-803-1511 Ali Aldera
 Cellular 651-666-3354 Ryan Fritz

2021 Freightliner - Van Chassis - MT-45 - General Motors 6.0L L96 - Va
 Lic # : YCA1506 Odometer In : 60487
 Unit # : 444040
 VIN # : 4UZAC2GA8 MCMR1651

Part Description	Qty	Sale	Ext	Labor Description	Ext
Job Supplies			6.880	Work Requested: Oil pressure varies wildly. no air out of dash blower.	n/c
				Labor	55.00
				Check oil level, good, last PM less than 3000 miles ago. No check engine lights on, running good. Please take this vehicle to dealer for warranty repairs.	
				Labor	27.50
				Inspect HVAC system, blend door actuator burnt out, order parts and will replace when parts arrive.	
				Labor	55.00
				Tremco plunger taped and plunger bent, straighten plunger and bend catch back in place.	
				[Recommendations]	
				PM due by 7/7/2023 or 61,974 miles to extend the life of your vehicle.	
				FAI due by 10/31/2023	

Org. Estimate 144.38 Revisions 0.00 Current Estimate 144.38

Labor:	137.50
Parts:	6.88
SubTotal:	144.38
Tax:	0.00
Total:	144.38
Bal Due:	\$144.38

[Payments -]

Vehicle Received: 1/1/-4713

Customer Number : 4

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com