Job Site Repair LLC

12015 Brockton Ln N Maple Grove, MN. 55369

Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231664

Ext

n/c

INVOICE Ref #: 447026 Printed Date: 05/05/2023 Work Completed: 05/02/2023

JND Deliveries - Jeff Schissler

2020 Ford - Transit-350 - 3.5L, V6 (213CI) VIN(8)

1800 Como Ave. Suite 200F

Lic # : YBY1994 Odometer In : 151825

Saint Paul, MN 55108 Cellular 612-385-0644

Unit #: 447026 VIN #: 1FDBW5P83 **LKB18547**

| Part Description | Qty | Sale | Ext | Labor Description |
|----------------------|-------|-------|-------|----------------------------------|
| Light bulb | 1.000 | 3.09 | 3.09 | Work Requested: Inspect lights |
| Lisc plate lite assy | 1.000 | 38.84 | 38.84 | Labor |
| Job Supplies | | | 5.500 | Inspect lights, replace burnt ou |

Labor 110.00
Inspect lights, replace burnt out drivers side turn signal lamp.
License plate light out, replace light and run new power wire to light to eliminate several splices in wire. All lights work properly after

repairs.

[Recommendations]

PM due by 6/23/2023 or 146,191 miles to extend the life of your vehicle

FAI due by 12/31/2023

Org. Estimate 160.52 Revisions 0.00 Current Estimate 160.52

Labor: 110.00 Parts: 47.43

SubTotal: Tax: 157.43 3.09 160.52

Total: Bal Due:

160.52 \$160.52

[Payments -]

Vehicle Received: 5/2/2023 Customer Number : 65

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com