

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
61777234	447572
DATE 12-16-2022	

MOTOR CARRIER OPERATOR Fed Ex Ground	INSPECTOR'S NAME (PRINT OR TYPE) Nick Lugowski
ADDRESS 1000 Fed Ex Drive	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE Pittsburgh, PA 15108	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER IFC3E4KK8MDC29738
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input checked="" type="checkbox"/> (OTHER) step Van	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED											
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System	✓			b. Front End Structure				13. WINDSHIELD WIPERS
✓			c. Brake Drums or Rotors	✓			c. Intermodal Container Securement Devices	✓			No missing, damaged, or inoperable wipers.
✓			d. Brake Hose	N/A			7. STEERING MECHANISM			14. MOTORCOACH SEATS	
✓			e. Brake Tubing	✓			a. Steering Wheel Free Play	N/A			Seats securely fastened to the vehicle structure.
✓			f. Low Pressure Warning Device	✓			b. Steering Column	✓			15. REAR IMPACT GUARD
N/A			g. Tractor Protection Valve	✓			c. Front Axle Beam/All Other Steering Components	✓			In place, securely attached, proper size, proper placement (see 393.86).
N/A			h. Air Compressor	✓			d. Steering Gear Box	✓			16. OTHER
N/A			i. Electric Brakes	✓			e. Pitman Arm	✓			List any other condition(s) which may prevent safe operation of this vehicle.
✓			j. Hydraulic Brakes	✓			f. Power Steering	✓			
N/A			k. Vacuum Systems	✓			g. Ball and Socket Joints	✓			
✓			l. Antilock Brake System	✓			h. Tie Rods and Drag Links	✓			
N/A			m. Automatic Brake Adjusters	✓			i. Nuts	✓			
			2. COUPLING DEVICES				8. SUSPENSION				
N/A			a. Fifth Wheels	✓			a. Axle Positioning Parts	✓			
N/A			b. Pintle Hooks	✓			b. Spring Assembly	✓			
N/A			c. Drawbar/Towbar Eye	✓			c. Torque, Radius or Tracking Components	✓			
N/A			d. Drawbar/Towbar Tongue	✓			9. FRAME				
N/A			e. Safety Devices	✓			a. Frame Members	✓			
N/A			f. Saddle-Mounts	✓			b. Tire and Wheel Clearance	✓			
			3. EXHAUST SYSTEM				c. Adjustable Axle Assemblies (Sliding Subframes)	✓			
✓			a. No leaks forward of/ directly below the driver/ sleeper compartment.	✓			10. TIRES				
N/A			b. Bus: No leaking/ discharging in violation of standard.	✓			a. Steer-Axle Tires	✓			
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	N/A			b. All Other Tires	✓			
			4. FUEL SYSTEM				c. Speed-Restricted Tires	✓			
✓			a. No visible leak.	✓			11. WHEELS AND RIMS				
✓			b. Fuel Tank Filler Cap	N/A			a. Lock or Side Ring	✓			
✓			c. Fuel tank securely attached.	✓			b. Wheels and Rims	✓			
			5. LIGHTING DEVICES				c. Fasteners	✓			
✓			All required lights/reflectors operable.	✓			d. Welds	✓			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.