

**ANNUAL VEHICLE INSPECTION REPORT**

VEHICLE HISTORY RECORD	
REPORT NUMBER <b>61777137</b>	FLEET UNIT NUMBER <b>447574</b>
DATE <b>12-15-2022</b>	

MOTOR CARRIER OPERATOR <b>FedEx Ground</b>	INSPECTOR'S NAME (PRINT OR TYPE) <b>Mike Ammermann</b>
ADDRESS <b>1000 FedEx Drive</b>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE <b>Pittsburgh PA 15108</b>	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER <b>1FC3E4KK8MDC27455</b>
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input checked="" type="checkbox"/> (OTHER) <b>step van</b>	INSPECTION AGENCY/LOCATION (OPTIONAL)

**VEHICLE COMPONENTS INSPECTED**

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	
<b>1. BRAKE SYSTEM</b>			a. Service Brakes	✓			<b>6. SAFE LOADING</b>			<b>12. WINDSHIELD GLAZING</b>		
✓			b. Parking Brake System	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).	
✓			c. Brake Drums or Rotors	✓			b. Front End Structure				<b>13. WINDSHIELD WIPERS</b>	
✓			d. Brake Hose	✓			c. Intermodal Container Securement Devices	✓			No missing, damaged, or inoperable wipers.	
✓			e. Brake Tubing	NA			<b>7. STEERING MECHANISM</b>			<b>14. MOTORCOACH SEATS</b>		
✓			f. Low Pressure Warning Device	✓			a. Steering Wheel Free Play	NA			Seats securely fastened to the vehicle structure.	
NA			g. Tractor Protection Valve	✓			b. Steering Column				<b>15. REAR IMPACT GUARD</b>	
NA			h. Air Compressor	✓			c. Front Axle Beam/All Other Steering Components	✓			In place, securely attached, proper size, proper placement (see 393.86).	
NA			i. Electric Brakes	✓			d. Steering Gear Box				<b>16. OTHER</b>	
NA			j. Hydraulic Brakes	✓			e. Pitman Arm				List any other condition(s) which may prevent safe operation of this vehicle.	
NA			k. Vacuum Systems	✓			f. Power Steering	✓				
NA			l. Antilock Brake System	✓			g. Ball and Socket Joints					
NA			m. Automatic Brake Adjusters	✓			h. Tie Rods and Drag Links					
<b>2. COUPLING DEVICES</b>			a. Fifth Wheels	✓			i. Nuts					
NA			b. Pintle Hooks	✓			j. Steering System					
NA			c. Drawbar/Towbar Eye	✓			<b>8. SUSPENSION</b>					
NA			d. Drawbar/Towbar Tongue	✓			a. Axle Positioning Parts					
NA			e. Safety Devices	✓			b. Spring Assembly					
NA			f. Saddle-Mounts	✓			c. Torque, Radius or Tracking Components					
<b>3. EXHAUST SYSTEM</b>			a. No leaks forward of/directly below the driver/sleeper compartment.	✓			<b>9. FRAME</b>					
✓			b. Bus: No leaking/discharging in violation of standard.	✓			a. Frame Members					
NA			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			b. Tire and Wheel Clearance					
✓			<b>4. FUEL SYSTEM</b>				c. Adjustable Axle Assemblies (Sliding Subframes)					
✓			a. No visible leak.	✓			<b>10. TIRES</b>					
✓			b. Fuel Tank Filler Cap	NA			a. Steer-Axle Tires					
✓			c. Fuel tank securely attached.	✓			b. All Other Tires					
<b>5. LIGHTING DEVICES</b>							c. Speed-Restricted Tires					
✓			All required lights/reflectors operable.	✓			<b>11. WHEELS AND RIMS</b>					
✓							a. Lock or Side Ring					
✓							b. Wheels and Rims					
✓							c. Fasteners					
✓							d. Welds					

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.