ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
61777138	447747
DATE	
01-03-2023	

MOTOR CARRIER OPERATOR: FedEx Ground

ADDRESS: 1000 FedEx Drive

CITY, STATE, ZIP CODE: Pittsburgh PA 15108

VEHICLE TYPE: ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☒ (OTHER) step van

INSPECTOR'S NAME (PRINT OR TYPE): Mike Ammermann

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER: 1F66F5KN9L0A10063

INSPECTION AGENCY/LOCATION (OPTIONAL):

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
✓			f. Low Pressure Warning Device
NA			g. Tractor Protection Valve
NA			h. Air Compressor
✓			i. Electric Brakes
✓			j. Hydraulic Brakes
NA			k. Vacuum Systems
✓			l. Antilock Brake System
NA			m. Automatic Brake Adjusters
			2. COUPLING DEVICES
NA			a. Fifth Wheels
NA			b. Pintle Hooks
NA			c. Drawbar/Towbar Eye
NA			d. Drawbar/Towbar Tongue
NA			e. Safety Devices
NA			f. Saddle-Mounts
			3. EXHAUST SYSTEM
✓			a. No leaks forward of/ directly below the driver/ sleeper compartment.
NA			b. Bus: No leaking/ discharging in violation of standard.
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
			4. FUEL SYSTEM
✓			a. No visible leak.
✓			b. Fuel Tank Filler Cap
✓			c. Fuel tank securely attached.
			5. LIGHTING DEVICES
✓			All required lights/reflectors operable.
			6. SAFE LOADING
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
✓			b. Front End Structure
NA			c. Intermodal Container Securement Devices
			7. STEERING MECHANISM
✓			a. Steering Wheel Free Play
✓			b. Steering Column
✓			c. Front Axle Beam/All Other Steering Components
✓			d. Steering Gear Box
✓			e. Pitman Arm
✓			f. Power Steering
✓			g. Ball and Socket Joints
✓			h. Tie Rods and Drag Links
✓			i. Nuts
✓			j. Steering System
			8. SUSPENSION
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
			9. FRAME
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
NA			c. Adjustable Axle Assemblies (Sliding Subframes)
			10. TIRES
✓			a. Steer-Axle Tires
✓			b. All Other Tires
NA			c. Speed-Restricted Tires
			11. WHEELS AND RIMS
NA			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds
			12. WINDSHIELD GLAZING
✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			13. WINDSHIELD WIPERS
✓			No missing, damaged, or inoperable wipers.
			14. MOTORCOACH SEATS
NA			Seats securely fastened to the vehicle structure.
			15. REAR IMPACT GUARD
✓			In place, securely attached, proper size, proper placement (see 393.86).
			16. OTHER
✓			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Copyright 2022 J. J. Keller & Associates, Inc.
Neenah, WI • JJKeller.com • (800) 327-6868
Printed in the USA

ORIGINAL