

**Job Site Repair LLC**  
12015 Brockton Ln N  
Maple Grove, MN. 55369  
Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231617**

**INVOICE**

Ref # : 449997

Printed Date: 04/29/2023

Work Completed: 04/28/2023

**Fern, Inc. - Darla Fern**  
1325 200th Street  
Baldwin, WI 54002  
Cellular 612-812-6584

2021 Freightliner - Van Chassis - MT-55 - General Motors 6.0L L96 - Va  
Lic # : GD83575 Odometer In : 47457  
Unit # : 449997  
VIN # : 4UZAC3GA6 MCMP7785

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	6.500	4.45	28.93	Work Requested: PM	n/c
Filter oil	1.000	10.35	10.35	PM Service	80.00
Transmission fluid	1.000	12.86	12.86	Change oil, oil filter, lube vehicle	
W/ Washer Fluid	1.000	3.39	3.39		
Job Supplies			4.000		
				<b>[ Recommendations ]</b> PM due by 8/28/2023 or 51,457 miles to extend the life of your vehicle. FAI due by 8/31/2023	

Org. Estimate 143.63 Revisions 0.00 Current Estimate 143.63

<b>Labor:</b>	<b>80.00</b>
<b>Parts:</b>	<b>59.53</b>
<b>SubTotal:</b>	<b>139.53</b>
<b>Tax:</b>	<b>4.10</b>
<b>Total:</b>	<b>143.63</b>
<b>Bal Due:</b>	<b>\$143.63</b>

[ Payments - ]

Vehicle Received: 4/28/2023

Customer Number : 16

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)