Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
231940

INVOICE

Ref # : 466793 Printed Date: 05/22/2023 **Work Completed: 05/19/2023**

JND Deliveries - Jeff Schissler
1800 Como Ave. Suite 200F
Saint Paul, MN 55108
Cellular 612-385-0644

2020 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
Lic # : YBZ9642 Odometer In : 35685
Unit # : 466793
VIN # : 1F66F5KN3 **L0A14495**

Part Description	Qty	Sale	Ext
245/70/19.5 DC RT600	1.000	251.55	251.55
Tire Disposal	1.000	15.00	15.00
Job Supplies			3.000

Labor Description	Ext
Work Requested: Nail in front right tire	n/c
Labor tire	60.00
Replace drivers side steer tire and balance, air to 100 PSI. Existing tire was at 3/32". Remove short screw from passenger side tire, did not penetrate tread no leaks, this tire good to run at 12/32"	
[Recommendations]	
PM due by 5/30/2023 or 34,397 miles to extend the life of your vehicle.	
FAI due by 7/31/2023	

Org. Estimate 348.10 Revisions 0.00 Current Estimate 348.10

Labor:	**60.00**
Parts:	**254.55**
Tire Fees:	**15.000**
SubTotal:	**329.55**
Tax:	**18.55**
Total:	**348.10**
Bal Due:	**$348.10**

[Payments -]

Vehicle Received: 5/19/2023

Customer Number : 65

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address:***jeff@jobsiterepair.com***

Copyright (c) 2023 Mitchell Repair Information Company, LLC invhrs 5.12.21kr