

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231899**

**INVOICE**

Ref # : 467111

Printed Date: 05/19/2023

Work Completed: 05/17/2023

**North Star Courier - Mitch Boeder**  
 7347 Sping Lake Road  
 Saint Paul, MN 55112  
 Cellular 507-351-5599

2020 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL  
 Lic # : YCB4518 Odometer In : 59162  
 Unit # : 467111  
 VIN # : 1F66F5KN2 L0A11362

Part Description	Qty	Sale	Ext	Labor Description	Ext
W/wiper blade	2.000	10.53	21.06	Work Requested: Federal Annual Inspection	n/c
Job Supplies			5.630	Labor	27.50
				Replace worn wiper blades	
				Inspection	85.00
				Vehicle Inspection & PASSED after above repairs	
				<b>[ Recommendations ]</b>	
				PM due by 7/20/2023 or 58,008 miles to extend the life of your vehicle.	
				FAI due by 5/31/2024	

Org. Estimate 140.77 Revisions 0.00 Current Estimate 140.77

<b>Labor:</b>	<b>112.50</b>
<b>Parts:</b>	<b>26.69</b>
<b>SubTotal:</b>	<b>139.19</b>
<b>Tax:</b>	<b>1.58</b>
<b>Total:</b>	<b>140.77</b>
<b>Bal Due:</b>	<b>\$140.77</b>

[ Payments - ]

Vehicle Received: 5/17/2023

Customer Number : 81

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)