

**Job Site Repair LLC**  
12015 Brockton Ln N  
Maple Grove, MN. 55369  
Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231729**

**INVOICE**

Ref # : 468078

Printed Date: 05/10/2023

Work Completed: 05/05/2023

**Gentle Delivery Inc. - Mikhail Kostyukevich**

17026 78th Place N  
Osseo, MN 55311  
Cellular 763-228-9536 Mike

2021 Freightliner - Van Chassis - MT-55 - General Motors 6.0L L96 - Va

Lic # : YBY9258

Odometer In : 40086

Unit # : 468078

VIN # : 4UZAC3GA6 MCMX8533

Part Description	Qty	Sale	Ext	Labor Description	Ext
245/70/19.5 DC RT600 Rogers	2.000	251.55	503.10	Work Requested: Replace front tires	n/c
Tire Disposal	2.000	15.00	30.00	Labor tire	80.00
Job Supplies			4.000	Replace steer tires and balance, air to 100 PSI	

**[ Recommendations ]**

PM due by 9/4/2023 or 44,083 miles to extend the life of your vehicle.

FAI due by 8/31/2023

Org. Estimate 654.96 Revisions 0.00 Current Estimate 654.96

<b>Labor:</b>	<b>80.00</b>
<b>Parts:</b>	<b>507.10</b>
<b>Tire Fees:</b>	<b>30.000</b>
<b>SubTotal:</b>	<b>617.10</b>
<b>Tax:</b>	<b>37.86</b>
<b>Total:</b>	<b>654.96</b>
<b>Bal Due:</b>	<b>\$654.96</b>

[ Payments - ]

Vehicle Received: 5/5/2023

Customer Number : 19

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)