

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231583**

**INVOICE**

Ref # : 468202

Printed Date: 04/27/2023

Work Completed: **04/26/2023**

**B Jackson Home Del. Inc - Bruce Jackson**  
 11331 Wildflower Drive N  
 Lake Elmo, MN 55042  
 Cellular 651-335-1167

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL  
 Lic # : YCA7373 Odometer In : 18271  
 Unit # : 468202  
 VIN # : 1F65F5KN3 **M0A10783**

Part Description	Qty	Sale	Ext	Labor Description	Ext
Oil 10W30 Citgard 600	8.000	4.45	35.60	Work Requested: PM	n/c
Filter Oil	1.000	12.28	12.28	PM Service	80.00
Job Supplies			4.000	Change oil, oil filter, lube vehicle	

**[ Recommendations ]**

PM due by 8/26/2023 or 22,271 miles to extend the life of your vehicle.  
 FAI due by 8/31/2023

Org. Estimate 135.41 Revisions 0.00 Current Estimate 135.41

<b>Labor:</b>	<b>80.00</b>
<b>Parts:</b>	<b>51.88</b>
<b>SubTotal:</b>	<b>131.88</b>
<b>Tax:</b>	<b>3.53</b>
<b>Total:</b>	<b>135.41</b>
<b>Bal Due:</b>	<b>\$135.41</b>

[ Payments - ]

Vehicle Received: 4/26/2023

Customer Number : 62

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)