

**Job Site Repair LLC**  
 12015 Brockton Ln N  
 Maple Grove, MN. 55369  
 Phone: 763-428-8891 Fax: 866-454-6909

**INVOICE**

**231903**

**INVOICE**

Ref # : 475498

Printed Date: 05/19/2023

Work Completed: 05/17/2023

**Dilly Logistics, Inc. - Vandan Vekaria**  
 7008 92nd Ave. N.  
 Brooklyn Park, MN 55445  
 Cellular 651-410-4911

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL  
 Lic # : PLF9072 Odometer In : 38018  
 Unit # : 475498  
 VIN # : 1F66F5KN3 M0A16698

Part Description	Qty	Sale	Ext	Labor Description	Ext
Muffler clamp	1.000	11.67	11.67	Work Requested: Exhaust hanging low and noisy	n/c
Job Supplies			5.500	Labor	110.00
				Inspect exhaust system, all clamps loose and exhaust pipes rotating, tighten all clamps from catalytic converter to muffler. Replace clamp at muffler, secure hanging hanger and adjust. Exhaust complete after repairs.	
				<b>[ Recommendations ]</b>	
				PM due by 8/17//2023 or 39,131 miles to extend the life of your vehicle.	
				FAI due by 12/31/2023	

Org. Estimate 128.05 Revisions 0.00 Current Estimate 128.05

<b>Labor:</b>	<b>110.00</b>
<b>Parts:</b>	<b>17.17</b>
<b>SubTotal:</b>	<b>127.17</b>
<b>Tax:</b>	<b>0.88</b>
<b>Total:</b>	<b>128.05</b>
<b>Bal Due:</b>	<b>\$128.05</b>

[ Payments - ]

Vehicle Received: 5/17/2023

Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: [www.jobsiterepair.com](http://www.jobsiterepair.com)

Email Address: [jeff@jobsiterepair.com](mailto:jeff@jobsiterepair.com)