Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
230701

INVOICE

Ref # : 475500 Printed Date: 02/25/2023 **Work Completed: 02/20/2023**

Dilly Logistics, Inc. - Vandan Vekaria
7008 92nd Ave. N.
Brooklyn Park, MN 55445
Cellular 651-410-4911

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
Lic # : PLF9074 Odometer In : 24624
Unit # : 475500
VIN # : 1F65F5KN6 **M0A14066**

Part Description	Qty	Sale	Ext
Job Supplies			4.130

Labor Description	Ext
Work Requested: Drivers door won't open	n/c
Labor	82.50

Inspect drivers door, found full of sand, pounds of sand on drivers step. Vacuum out tracks and clean up sand. Wash out drivers and passenger door tracks. Lube and adjust doors, doors work fine after repairs.

[Recommendations]
PM due by 4/13/2023 or 23,610 miles to extend the life of your vehicle.
FAI due by 11/30/2023

Org. Estimate 86.63 Revisions 0.00 Current Estimate 86.63

Labor:	**82.50**
Parts:	**4.13**
SubTotal:	**86.63**
Tax:	**0.00**
Total:	**86.63**
Bal Due:	**$86.63**

[Payments -]

Vehicle Received: 2/20/2023

Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com Email Address: ***jeff@jobsiterepair.com***

Copyright (c) 2023 Mitchell Repair Information Company, LLC invhrs 5.12.21kr