Job Site Repair LLC
12015 Brockton Ln N
Maple Grove, MN. 55369
Phone: 763-428-8891 Fax: 866-454-6909

INVOICE
225201

INVOICE

Ref # : 475503 Printed Date: 12/15/2022 **Work Completed: 12/13/2022**

Dilly Logistics, Inc. - Vandan Vekaria
7008 92nd Ave. N.
Brooklyn Park, MN 55445
Cellular 651-410-4911

2021 Ford - F59/F53 Stripped Chassis - Ford 7.3L 99N 8 CYL
Lic # : PLF9069 Odometer In : 27482
Unit # : 475503
VIN # : 1F65F5KN7 **M0A16764**

Part Description	Qty	Sale	Ext
Oil 10W30 Citgard 600	8.500	4.22	35.87
Filter oil	1.000	8.36	8.36
Light Amber LED	1.000	8.31	8.31
Job Supplies			5.380

Labor Description	Ext
Work Requested: PM	n/c
PM Service	80.00
Change oil, oil filter, lube vehicle	
Labor	27.50
Inspect lights, replace burnt out right hood marker light All lights work properly after repairs.	

[Recommendations]
PM due by 4/13/2023 or 31,482 miles to extend the life of your vehicle.
FAI due by 12/31/2023

Org. Estimate 169.37 Revisions 0.00 Current Estimate 169.37

Labor:	**107.50**
Parts:	**57.92**
SubTotal:	**165.42**
Tax:	**3.95**
Total:	**169.37**
Bal Due:	**$169.37**

[Payments -]

Vehicle Received: 12/13/2022

Customer Number : 92

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com Email Address: ***jeff@jobsiterepair.com***

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 5.12.21kr