

ANNUAL VEHICLE INSPECTION REPORT

**VEHICLE HISTORY RECORD**

REPORT NUMBER	61777136
FLEET UNIT NUMBER	475505
DATE	12-12-2022

MOTOR CARRIER OPERATOR: **FedEx Ground**  
 ADDRESS: **1000 FedEx Drive**  
 CITY, STATE, ZIP CODE: **Pittsburgh PA 15108**  
 VEHICLE TYPE:  TRACTOR  TRAILER  TRUCK  BUS  (OTHER) **Step van**  
 VEHICLE IDENTIFICATION (AND COMPLETE)  LIC. PLATE NO.  VIN  OTHER: **1F65F5KN6M0A16769**  
 INSPECTION AGENCY/LOCATION (OPTIONAL):  
 THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.  YES

VEHICLE COMPONENTS INSPECTED		OK	NEEDS REPAIR	REPAIRED DATE	OK	NEEDS REPAIR	REPAIRED DATE
<b>1. BRAKE SYSTEM</b>							
a. Service Brakes							
b. Parking Brake System							
c. Brake Drums or Rotors							
d. Brake Hose							
e. Brake Tubing							
f. Low Pressure Warning Device							
g. Tractor Protection Valve							
h. Air Compressor							
i. Electric Brakes							
j. Hydraulic Brakes							
k. Vacuum Systems							
l. Antilock Brake System							
m. Automatic Brake Adjusters							
<b>2. COUPLING DEVICES</b>							
a. Fifth Wheels							
b. Pintle Hooks							
c. Drawbar/Towbar Eye							
d. Drawbar/Towbar Tongue							
e. Safety Devices							
f. Saddle-Mounts							
<b>3. EXHAUST SYSTEM</b>							
a. No leaks forward of directly below the driver/sleeper compartment.							
b. Bus: No leaking/discharging in violation of standard.							
c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.							
<b>4. FUEL SYSTEM</b>							
a. No visible leak.							
b. Fuel Tank Filler Cap							
c. Fuel tank securely attached.							
<b>5. LIGHTING DEVICES</b>							
All required lights/reflector operable.							
<b>6. SAFE LOADING</b>							
a. Vehicle parts, load, dunnage, spare tire, etc., secured.							
b. Front End Structure							
c. Intermodal Container							
d. Secured							
<b>7. STEERING MECHANISM</b>							
a. Steering Wheel Free Play							
b. Steering Column							
c. Front Axle Beam/All Other Steering Components							
d. Steering Gear Box							
e. Pitman Arm							
f. Power Steering							
g. Ball and Socket Joints							
h. Tie Rods and Drag Links							
i. Nuts							
j. Steering System							
<b>8. SUSPENSION</b>							
a. Axle Positioning Parts							
b. Spring Assembly							
c. Torque, Radius or Tracking Components							
<b>9. FRAME</b>							
a. Frame Members							
b. Tire and Wheel Clearance							
c. Adjustable Axle Assemblies (Sliding Subframes)							
<b>10. TIRES</b>							
a. Steer-Axle Tires							
b. All Other Tires							
c. Speed-Restricted Tires							
<b>11. WHEELS AND RIMS</b>							
a. Lock or Side Ring							
b. Wheels and Rims							
c. Fasteners							
d. Welds							
<b>12. WINDSHIELD GLAZING</b>							
No cracks, discoloration, obstructions, etc. (see 393.60 for exceptions).							
<b>13. WINDSHIELD WIPERS</b>							
No missing, damaged, or inoperable wipers.							
<b>14. MOTORCOACH SEATS</b>							
Seats securely fastened to the vehicle structure.							
<b>15. REAR IMPACT GUARD</b>							
In place, securely attached, proper size, proper placement (see 393.86).							
<b>16. OTHER</b>							
List any other condition(s) which may prevent safe operation of this vehicle.							

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.