

Job Site Repair LLC
 12015 Brockton Ln N
 Maple Grove, MN. 55369
 Phone: 763-428-8891 Fax: 866-454-6909

INVOICE

231757

INVOICE

Ref # : 84993

Printed Date: 05/11/2023

Work Completed: **05/09/2023**

JJH Transport Corp. - Josh Hanson

14355 Irish Ave. N.
 Hugo, MN 55038
 Cellular 651-558-1239

2007 Freightliner - Van Chassis - MT-55 - Mercedes-Benz MBE 900 EP
 Lic # : YBW6956 Odometer In : 348380
 Unit # : 84993
 VIN # : 4UZAARCP8 7CY32155

Part Description	Qty	Sale	Ext	Labor Description	Ext
Filter Fuel	1.000	27.75	27.75	Work Requested: Put gas in diesel tank	n/c
Filter Fuel	1.000	30.90	30.90	Labor	275.00
Fuel	1.000	99.75	99.75	Drain contaminated fuel from tank, blow out fuel lines and replace fuel filters. put 25 gallons of diesel in tank and start engine.	
W/wiper blade	2.000	10.53	21.06	Appears to be running good, no damage to engine found at this time.	
Light amber LED	1.000	24.47	24.47	Labor	27.50
Job Supplies			16.500	Replace worn wiper blades	
				Labor	27.50
				Inspect lights, replace burnt out passenger side hood marker light. All lights work properly after repairs.	

Org. Estimate 558.11 Revisions 0.00 Current Estimate 558.11

Labor:	330.00
Parts:	220.43
SubTotal:	550.43
Tax:	7.68
Total:	558.11
Bal Due:	\$558.11

[Payments -]

Vehicle Received: 5/9/2023

Customer Number : 29

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Visit us on the web: www.jobsiterepair.com

Email Address: jeff@jobsiterepair.com